

GRIT BIN REPORT FOR CHAR VALLEY PARISH COUNCIL MEETING ON MONDAY 21 JUNE 2021

GRIT BIN COMPANIES FOUND ON THE WEB

NAME OF COMPANY	CAPACITY	COST INCLUDING VAT	ID NO	DIMENSIONS
Barriers Direct	200 litres	£136.33	22138	1020 W x 520 D x 720 H yellow
Safety Buyer	200 litres	£119.99	08-0100	Ditto yellow
Glaston **	115 litres	£130.90	22137	800 W x 474 D x 605 H yellow

** Installed by Dorset Council at the Five Bells after being demolished by the recycle lorry.

This bin needs to be repositioned so that it is sideways to the car park because in its present position, when there is inclement weather, the lid blows open and grit gets washed down the road.

BINS WHICH NEED REPLACING

LOCATION OF BIN	STATE OF REPAIR
Stanton St Gabriel Shedbush Lane	No lid
Whitchurch Becklands Hill	Broken base
Ryall Hillside Cottage	Broken lid
Fishponds Peters Gore	Broken hinge
Monkton Wyld at Cross roads	Broken hinge and corner

During this current survey several bins were completely buried under stinging nettles etc. May I suggest that a marker be placed by these bins to avoid the mechanical verge machines demolishing them during their annual cutting.

GRIT NEEDED TO FILL THE BINS WILL BE REPORTED ON AT A FUTURE MEETING.